


100 PSI (7 BAR) VARIOHM EUROSENSOR PRESSURE SENSOR OPS-504




CALIBRATION

0 Psi G = 0.500v
100 Psi G = 4.500v




22mm (7/8") Across Flats



Part No. OPS-504

WIRING LOOKING INTO SENSOR

PIN	Description
A	Sensor Ground
B	5 Volts
C	Signal



CONNECTOR KIT

CPS-010



Push wire through connector. Crimp on terminal.
Pull wire / terminal back into connector.

